CEDAR CAMPUS / REPORT EXAMPLE / 25 OCT 2026

Asbestos building survey

Administration / Technical Services / Training Hall

Project summary	Recorded information
Project reference	EX-041
Field inspection	24 Oct 2026
Laboratory return	EX-LAB-041 / 25 Oct 2026 / 2 source pages
Sample inventory	6 bulk specimens / EX-A01 through EX-C02
Laboratory information	Reviewed example wording
Professional conclusion	Review pending; not approved or issued

Contents

Eight fixed pages connect the field inventory, laboratory record and report evidence.

Scope, purpose, methods and property context 2

Building summaries and specimen results 3

Site plan 4

Conclusion, discussion and references 5

Appendix 1 - Laboratory source record 6

Appendix 2 - Chain of custody 7

Credential and review-role records 8

Laboratory approval does not approve professional conclusions, sign this document or authorize issuance.

Scope and survey context

Scope

Six identified material locations were recorded across Administration, Technical Services and Training Hall at Cedar Campus. The record covers the listed sample locations and represented material extents. Concealed materials, unsampled areas and unlisted layers fall outside this record.

Purpose

Document the sampled materials and locations, retain laboratory findings and provide source records for qualified professional review.

Methods / Protocol

The inspector recorded each building, area, material description and extent, then assigned a unique sample ID. Six bulk specimens were listed on the COC for polarized light microscopy (PLM), with next-day turnaround requested. Material extents in square feet or linear feet describe the represented material; they are not specimen quantities.

Property Details

Cedar Campus comprises three building groups. Administration is west of the site access route; Technical Services is northeast; Training Hall is southeast. The page 4 schematic identifies the six recorded locations. No construction date, building dimensions, occupancy or condition is inferred.

Introduction

Field collection took place on 24 October 2026. Laboratory documents returned on 25 October 2026. Proposed sample matches require explicit human review before laboratory information enters the reporting workflow. This limited website illustration does not establish sampling adequacy or regulatory compliance.

Building and area summaries

Administration

Reception ceiling: 48 sq ft of white troweled ceiling finish (EX-A01). East corridor: 120 sq ft of brown floor tile (EX-A02).

Technical Services

Plant room: 18 l ft of white pipe insulation (EX-B01). Service corridor: 64 sq ft of grey wallboard (EX-B02).

Training Hall

Main hall ceiling: 96 sq ft of white acoustic ceiling tile (EX-C01). Store room: 24 sq ft of black floor-tile adhesive (EX-C02).

Sampling and laboratory results

All six submitted specimen IDs match the field inventory and COC. Only reviewed source wording appears in the reviewed example. The pending example holds every result cell for human approval.


Specimen ID	Building / location	Laboratory result	Source / review
EX-A01	Administration / Reception ceiling	Not Detected	Page 1 / Reviewed
EX-A02	Administration / East corridor	2% Chrysotile	Page 1 / Reviewed
EX-B01	Technical Services / Plant room	5% Chrysotile	Page 1 / Reviewed
EX-B02	Technical Services / Service corridor	Not Detected	Page 1 / Reviewed
EX-C01	Training Hall / Main hall ceiling	Not Detected	Page 2 / Reviewed
EX-C02	Training Hall / Store room	3% Chrysotile	Page 2 / Reviewed

Result wording is specimen-specific. Review of professional conclusions remains pending in both examples.

SCHEMATIC LOCATION RECORD / NOT TO SCALE

Site Plan

Three building footprints retain the same specimen identities as the field inventory, COC and laboratory return.



Schematic site layout - not to scale. Dots identify the six recorded locations.

Text description

Schematic, not to scale. Administration is west, Technical Services northeast and Training Hall southeast. Administration contains EX-A01 at the reception ceiling and EX-A02 in the east corridor. Technical Services contains EX-B01 in the plant room and EX-B02 in the service corridor. Training Hall contains EX-C01 at the main hall ceiling and EX-C02 in the store room.

The schematic illustrates relationships between records. It is not a survey drawing, measured floor plan or assertion of complete site coverage.

Conclusion and supporting references

Conclusion - professional review pending

Laboratory wording has been reviewed for this fictional example. Specimens EX-A02, EX-B01 and EX-C02 record chrysotile; EX-A01, EX-B02 and EX-C01 record Not Detected. A qualified reviewer must still assess the source documents, survey scope, sampling adequacy and material condition before approving professional conclusions.

Specimen-level findings do not determine the status of unsampled areas, concealed materials or separate layers. No remediation direction, clearance, compliance finding or statement that a building is asbestos-free is supplied.

Additional Discussion

EX-B02 represents the submitted wallboard specimen only; it does not establish a result for an unlisted joint-compound or skim-coat layer. Each result remains tied to its own specimen and source page. Corrections retain source references. Approving laboratory information does not sign or issue the report.

References

Project field record EX-041; six-specimen chain of custody dated 24 October 2026; laboratory return EX-LAB-041 dated 25 October 2026, source pages 1 and 2. These are fictional website records, not external research or verified customer documents.

Review status

Laboratory information: reviewed example wording. Professional conclusion: review pending. Report approval: pending. Issuance: not authorized.

Appendix 1 - Laboratory source record

EX-LAB-041 / PLM / returned 25 Oct 2026 / original source pages 1-2

This appendix retains source-page references. In the pending version, all six result cells remain held; no analytical value is exposed here before review.

Specimen ID	Material description	Method	Reported result	Source page
EX-A01	White troweled ceiling finish	PLM	Not Detected	1
EX-A02	Brown floor tile	PLM	2% Chrysotile	1
EX-B01	White pipe insulation	PLM	5% Chrysotile	1
EX-B02	Grey wallboard	PLM	Not Detected	1
EX-C01	White acoustic ceiling tile	PLM	Not Detected	2
EX-C02	Black floor-tile adhesive	PLM	3% Chrysotile	2

Source and approval boundary

The original illustrative laboratory return remains a separate two-page source document. This one-page report appendix is a source-linked summary, not an altered laboratory-issued report. It identifies no real laboratory, accreditation, analyst or signatory.

The exact source wording is retained after laboratory review. Professional report conclusions remain pending.

Appendix 2 - Chain of custody

EX-041 / Cedar Campus / 24 Oct 2026 / PLM / TAT ND (next day)

Set 01 Sample ID: EX-A01 Description: White troweled ceiling finish Location: Administration - Reception ceiling Amount: 48 sq ft Collected: 09:10 Category: SM TAT: ND Analysis: PLM	Set 02 Sample ID: EX-A02 Description: Brown floor tile Location: Administration - East corridor Amount: 120 sq ft Collected: 09:30 Category: MISC TAT: ND Analysis: PLM
Set 03 Sample ID: EX-B01 Description: White pipe insulation Location: Technical Services - Plant room Amount: 18 l ft Collected: 10:05 Category: TSI TAT: ND Analysis: PLM	Set 04 Sample ID: EX-B02 Description: Grey wallboard Location: Technical Services - Service corridor Amount: 64 sq ft Collected: 10:25 Category: MISC TAT: ND Analysis: PLM
Set 05 Sample ID: EX-C01 Description: White acoustic ceiling tile Location: Training Hall - Main hall ceiling Amount: 96 sq ft Collected: 11:05 Category: MISC TAT: ND Analysis: PLM	Set 06 Sample ID: EX-C02 Description: Black floor-tile adhesive Location: Training Hall - Store room Amount: 24 sq ft Collected: 11:25 Category: MISC TAT: ND Analysis: PLM
Set: _____ Sample ID: _____ Description: _____ Location(s): _____ Amount: _____ Unit: _____ Category: SM / TSI / MISC TAT: SD / ND Analysis: PLM	Set: _____ Sample ID: _____ Description: _____ Location(s): _____ Amount: _____ Unit: _____ Category: SM / TSI / MISC TAT: SD / ND Analysis: PLM
Set: _____ Sample ID: _____ Description: _____ Location(s): _____ Amount: _____ Unit: _____ Category: SM / TSI / MISC TAT: SD / ND Analysis: PLM	Set: _____ Sample ID: _____ Description: _____ Location(s): _____ Amount: _____ Unit: _____ Category: SM / TSI / MISC TAT: SD / ND Analysis: PLM
Set: _____ Sample ID: _____ Description: _____ Location(s): _____ Amount: _____ Unit: _____ Category: SM / TSI / MISC TAT: SD / ND Analysis: PLM	Set: _____ Sample ID: _____ Description: _____ Location(s): _____ Amount: _____ Unit: _____ Category: SM / TSI / MISC TAT: SD / ND Analysis: PLM

Material extents are represented areas or lengths, not specimen quantities.

Sampled By: Inspector role · 24 Oct 2026 · 09:10–11:25

Relinquished By: Inspector role · 24 Oct 2026, 12:10

Received By: Laboratory intake role · 24 Oct 2026, 13:00

Credential and review-role records

This fictional example demonstrates where supporting credential records and review roles belong. It supplies no credential IDs, certificates, seals, signatures or assertion of verified qualifications.

Record / role	Example record	Status
Laboratory credentials	No laboratory is represented	Not supplied
Inspector credentials	Example field-inspector role only	Not supplied
Consultant credentials	Example professional-review role only	Not supplied
Company business license	No real firm credential is represented	Not supplied
Laboratory review	Explicit review action in website demonstration	Reviewed example
Professional report review	Separate qualified review and conclusion	Pending
Report signature / issuance	No signature or issuance action	Not authorized

Before a real report is issued

An authorized team verifies applicable credentials, source evidence, sample interpretation, professional conclusions and the final deliverable through its agreed workflow. This website example is not evidence that those steps occurred for a real project.

Fictional website example - not issued