EX-LAB-041 / source page 1 of 2 / returned 25 Oct 2026

Laboratory return

Project: EX-041 | Site: Cedar Campus | Requested method: PLM

Illustrative specimen results for the website walkthrough. This document does not identify a laboratory, accreditation, analyst or signatory.

Specimen ID	Material description	Method	Reported result
EX-A01	White troweled ceiling finish	PLM	Not Detected
EX-A02	Brown floor tile	PLM	2% Chrysotile
EX-B01	White pipe insulation	PLM	5% Chrysotile
EX-B02	Grey wallboard	PLM	Not Detected

Source record

These 4 records belong to source page 1. Wording is retained exactly in the reviewed report example; it is held in the pending report example.

Interpretation boundary

A specimen result describes the submitted material. It does not establish the status of unsampled areas, concealed materials or separate unlisted layers. Professional interpretation and report approval remain separate from laboratory intake.

No real laboratory, customer, credential, signature or seal is represented.

EX-LAB-041 / source page 2 of 2 / returned 25 Oct 2026

Laboratory return

Project: EX-041 | Site: Cedar Campus | Requested method: PLM

Illustrative specimen results for the website walkthrough. This document does not identify a laboratory, accreditation, analyst or signatory.

Specimen ID	Material description	Method	Reported result
EX-C01	White acoustic ceiling tile	PLM	Not Detected
EX-C02	Black floor-tile adhesive	PLM	3% Chrysotile

Source record

These 2 records belong to source page 2. Wording is retained exactly in the reviewed report example; it is held in the pending report example.

Interpretation boundary

A specimen result describes the submitted material. It does not establish the status of unsampled areas, concealed materials or separate unlisted layers. Professional interpretation and report approval remain separate from laboratory intake.

No real laboratory, customer, credential, signature or seal is represented.